

SERVICE BULLETIN #32

RE: HYDRAULIC HOSES and TORQUE TUBE REPLACEMENT

Effective April 1995, Little Beaver has replaced the two piece torque tube on the hydraulic with a newly designed one piece torque tube. If ordering a replacement torque tube, please order Part # 9092-M . When needing to replace hoses and you have the two piece torque tube, we ask that you order them from Little Beaver by part number specified in your owner's manual. If not ordering by part number for power source serial numbers H-0001 through H-3252, ***do not*** exceed the following maximum hose assembly lengths. Longer hose assemblies may allow the torque tube to uncouple, causing serious personal injury.

MAXIMUM OVERALL HOSE LENGTHS

Handle - Pressure/Return hose 36" over fittings
Power Source - Pressure hose 74 1/4" over fittings
Power Source - Return hose 68" over fittings

FOR MORE INFORMATION CONTACT:

LITTLE BEAVER, INC.

P. O. Box 840, Livingston, Texas 77351
PH: 936/327-3121 or Fax: 936/327-4025
EMAIL: sales@littlebeaver.com