

SERVICE BULLETIN #6

RE: HYDRAULIC RETURN LINE FILTER

To obtain extended hydraulic component life, it is recommended that the hydraulic return line filter be changed after the first fifteen hours of operation. The filter should be changed with each oil change, yearly, or after five hundred (500) hours of operation; whichever comes first.

ORDER PART #30280

Cross Reference Part Numbers are as follows:

Parker # 921999-10C

Zinga # AE-10

Ripley # DP-752-10

Amback # S-28

Fram # P-1653-A

FOR MORE INFORMATION CONTACT:

LITTLE BEAVER, INC.

P. O. Box 840, Livingston, Texas 77351

PH: 936/327-3121 or Fax: 936/327-4025

EMAIL: sales@littlebeaver.com